All,

Hereby a short summary of the items discussed on site with ODRN.

Attendees:



On site we assessed the situation of the E-filters/Precips,

Ducts at DeNox side

We went to see the ducts on the DeNox side.

Initially we thought we couldn't reach the top part of the duct for asbestos removal.

While carrying out the removal of tin and rockwool we managed to reach all parts of the duct, even the top part.

Therefore, we do not need to use the Article 37 document for this part of the plant.

Duct in between the E-filters.

5.1.2e | Project Manager

For the duct in between the E-filters we need to use the Article 37 document.

It is not possible to remove the asbestos safely in the current situation.

We agreed on displacing the duct to ground level and remove the asbestos on ground level.

The Article 37 document will be used for this part of the job.

Removal of the duct and removing the asbestos will be carried out before the blow down.

The other asbestos materials mentioned in the survey can and will be removed before the blow down of the E-filters.

Best regards,



Your vision, our solution. Engineering with a difference.

Company Reg No: 1892133. This message (and any associated files) is intended only for the use of the individual or entity to which it is addressed and may contain information that is confidential, subject to copyright or constitutes a trade secret. If you are not the intended recipient you are hereby notified that any dissemination, copying or distribution of this message, or files associated with this message, is strictly prohibited. If you have received this message in error, please notify us immediately by replying to the message and deleting it from your computer. Messages sent to and from us may be monitored. Internet communications cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, arrive late or incomplete, or contain viruses. Therefore, we do not accept responsibility for any errors or omissions that are present in this message, or any attachment, that have arisen as a result of e-mail transmission. If verification is required, please request a hard-copy version. Any views or opinions presented are solely those of the author and do not necessarily represent those of the company.

44291914 0140